

K-LITE


Base plate $\square 150 \times 4\text{thk}$



2 Nos. of
M10 Nut


2 Nos. of Plain
& Spring washer

300



Cable entry hole $\varnothing 35$

3 Elongated Holes 20×12
to suit M10 bolts at PCD 90



M36