

K-LITE	IMPACT RESISTANCE TEST REPORT	Doc. No. KL/LAB/IKT1149
		Rev. No. 00


Product / EUT Details

Product Name	SUDO - OPEN
Product ID	2741
Test Location	K-LITE Testing Laboratory
Report Date	23/05/21
Reference Sl. No.	SUDO - OPEN/150/IKT1149

(IK TEST) – Conforming to IEC 60598-1

Test Equipment	IK PENDULUM HAMMER / BALL DROP TEST(Refer figure below)
Test Procedure	IK03
Impact Energy (J)	0.35J
Test Date	23/05/21
No of Impact	3
Drop Height	140mm

Requirement	Results	Remarks
EUT should not have any visual damage and shall work in normal condition after the impact test.	- No visible damage was observed on the EUT after completion of the mechanical impact test. - EUT was working in normal condition after the impact test. - Therefore the EUT met the requirement of IK.	P
P→ Passed (Meets requirement); F→ Failed (Does not meet requirement); NA→ Limits of Performance Not Applicable.		



1.This report refers only to the particular item(s) submitted for testing. The results reported in this report are valid at the time of, and under the stipulated conditions of measurement
2.This report shall not be reproduced, except in full, unless written permission for the publication of an approved abstract has been obtained from the Director, K-LITE, Chennai-600058

K. Mohan Rao
Tested by
Kuncham Mohan Rao
Jr. Engineer Illumination – OPTIC LAB

Akram Basha
Reviewed by
Akram Basha.H
TL – OPTIC LAB

Premkumar
Witnessed by
Premkumar. P
Head - QC

Muthukumar
Approved by
Muthukumar.C.R
Manager - Design

K-LITE	IMPACT RESISTANCE TEST REPORT	Doc. No. KL/LAB/IKT1151
		Rev. No. 00

Product / EUT Details

Product Name	SUDO MINI - OPEN
Product ID	2745
Test Location	K-LITE Testing Laboratory
Report Date	23/05/21
Reference Sl. No.	SUDO MINI - OPEN/152/IKT1151

(IK TEST) – Conforming to IEC 60598-1

Test Equipment	IK PENDULUM HAMMER / BALL DROP TEST(Refer figure below)
Test Procedure	IK03
Impact Energy (J)	0.35J
Test Date	23/05/21
No of Impact	3
Drop Height	140mm

Requirement	Results	Remarks
EUT should not have any visual damage and shall work in normal condition after the impact test.	- No visible damage was observed on the EUT after completion of the mechanical impact test. - EUT was working in normal condition after the impact test. - Therefore the EUT met the requirement of IK.	P
P→ Passed (Meets requirement); F→ Failed (Does not meet requirement); NA→ Limits of Performance Not Applicable.		



1.This report refers only to the particular item(s) submitted for testing. The results reported in this report are valid at the time of, and under the stipulated conditions of measurement
2.This report shall not be reproduced, except in full, unless written permission for the publication of an approved abstract has been obtained from the Director, K-LITE, Chennai-600058

G. Bal Murugan
Tested by

Balamurugan.S
Jr. Engineer Illumination – OPTIC LAB

Ag
Reviewed by

Akram Basha.H
TL – OPTIC LAB

Premkumar
Witnessed by

Premkumar. P
Head - QC

Muthukumaran
Approved by

Muthukumaran.C.R
Manager - Design

K-LITE	IMPACT RESISTANCE TEST REPORT	Doc. No. KL/LAB/IKT1150
		Rev. No. 00


Product / EUT Details

Product Name	SUDO - OPEN
Product ID	2753
Test Location	K-LITE Testing Laboratory
Report Date	23/05/21
Reference Sl. No.	SUDO - OPEN/151/IKT1150

(IK TEST) – Conforming to IEC 60598-1

Test Equipment	IK PENDULUM HAMMER / BALL DROP TEST(Refer figure below)
Test Procedure	IK03
Impact Energy (J)	0.35J
Test Date	23/05/21
No of Impact	3
Drop Height	140mm

Requirement	Results	Remarks
EUT should not have any visual damage and shall work in normal condition after the impact test.	- No visible damage was observed on the EUT after completion of the mechanical impact test. - EUT was working in normal condition after the impact test. - Therefore the EUT met the requirement of IK.	P
P→ Passed (Meets requirement); F→ Failed (Does not meet requirement); NA→ Limits of Performance Not Applicable.		



1.This report refers only to the particular item(s) submitted for testing. The results reported in this report are valid at the time of, and under the stipulated conditions of measurement
2.This report shall not be reproduced, except in full, unless written permission for the publication of an approved abstract has been obtained from the Director, K-LITE, Chennai-600058

S. Balamurugan

Tested by

Balamurugan.S

Jr. Engineer Illumination – OPTIC LAB

Akram Basha

Reviewed by

Akram Basha.H

TL – OPTIC LAB

Premkumar P

Witnessed by

Premkumar. P

Head - QC

Muthukumar C.R

Approved by

Muthukumar.C.R

Manager - Design