

IMPACT RESISTANCE TEST REPORT

Doc. No. KL/LAB/IKT1148

Rev. No. 00

Product / EUT Details

Product Name	SUDO EXTENDED - OPEN	
Product ID	2773	
Test Location	K-LITE Testing Laboratory	
Report Date	23/05/21	
Reference Sl. No.	SUDO EXTENDED - OPEN/149/IKT1148	

(IK TEST) - Conforming to IEC 60598-1

Test Equipment	IK PENDULUM HAMMER / BALL DROP TEST(Refer figure below	
Test Procedure	IK03	
Impact Energy (J)	0.35J	
Test Date	23/05/21	
No of Impact	3	
Drop Height	140mm	

Requirement	Results	Remarks
EUT should not have any visual damage and shall work in normal condition after the impact test.	- No visible damage was observed on the EUT after completion of the mechanical impact test EUT was working in normal condition after the impact test Therefore the EUT met the requirement of IK.	Р

P→ Passed (Meets requirement); F→ Failed (Does not meet requirement); NA→ Limits of Performance Not Applicable.



1. This report refers only to the particular item(s) submitted for testing. The results reported in this report are valid at the time of, and under the stipulated conditions of measurement 2. This report shall not be reproduced, except in full, unless written permission for the publication of an apported abstract has been obtained from the Director, K-LITE, Chennai-600058

Witnessed by

Kuncham Mohan Rao

Akram Basha.H

Premkumar. P

Muthukumaran.C.R

Jr. Engineer Illumination – OPTIC LAB

TL - OPTIC LAB

Head - QC

Manager - Design